

NO. OF COPIES RECEIVED	5
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND	FICE
OPER	OR

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

☐ OIL ☐ GAS WELL ☐ OTHER- Dry Hole		5a. Indicate Type of Lease State ☐ Fee ☒
1. Name of Operator Cities Service Oil Company ✓		6. Name of Lease Holder Tracy C Com.
3. Address of Operator Box 1919 - Midland, Texas 79701		8. Well No. 1
4. Location of Well UNIT LETTER <u>H</u> <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>32</u> TOWNSHIP <u>21S</u> RANGE <u>27E</u> N.M.P.M.		10. Field No., Pool, or Well Unit Undesignated Morrow
15. Elevation (Show whether DF, RT, GP, etc.) 3150' GR		12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPER. ☐	REPAIR AND MAINTENANCE ☒
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	OTHER ☐

17. Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of completion.)
SEE RULE 1103.

T. 11,725' Shale. Plugged and abandoned. This well was plugged and abandoned in the following manner:

1. Spotted a 40 sack cement plug across top of Morrow (11046') @ 11,100' - 11,000'.
2. Spotted a 40 sack cement plug across top of Strawn (10050') @ 10,100' - 10,000'.
3. Spotted a 40 sack cement plug across top of Canyon (9398') @ 9,450' - 9,350'.
4. Spotted a 40 sack cement plug across top of Wolfcamp (8724') @ 8,775' - 8,675'.
5. Spotted a 40 sack cement plug across top of 2nd. Bone Springs Sand (7050') @ 7,100' - 7,000'.
6. Spotted a 40 sack cement plug across top of 1st. Bone Springs Sand (6290') @ 6,350' - 6,250'.
7. Spotted a 40 sack cement plug across top of Bone Springs (5078') @ 5,125' - 5,025'.
8. Spotted a 40 sack cement plug $\frac{1}{2}$ in and $\frac{1}{2}$ out of 9-5/8" csg. shoe (3003') @ 3,050' - 2,950'.
9. Spotted a 10 sack cement surface plug in top of 9-5/8" csg. @ 58' - 0' and installed a 1" dry hole marker extending 4' above the surface to designate a plugged and abandoned location.

This location will be cleared of all debris and equipment and your office will be notified for final inspection.

Mr. Leon Bergstron with N.M.O.C.C., Artesia, New Mexico, witnessed plugging.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Edwin TITLE Region Operation Manager DATE April 30, 1975

APPROVED BY Frank Bergstron TITLE SUPERVISOR, DISTRICT II DATE JUL 15 1975

CONDITIONS OF APPROVAL, IF ANY: