

Details of bop test



Great Western Drilling Company

Burton State #1

11/19/72

Contractor: Moran Drlg. Rig 7

Test by Yellow Jacket Tools and Services, Inc.



The above is a transposition of the pressure recorder charts covering test to the blowout control equipment in service on your well drilling in the Carlsbad, New Mexico Area, Midland District, Texas. Test was made with test plug landed in casing head with the following test results:

Arrived location - crew working on rig.