

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NO.	
2. NAME OF OPERATOR Cities Service Oil Company ✓		8. FARM OR LEASE NO. Government	
3. ADDRESS OF OPERATOR Box 1919 - Midland, Texas 79701		9. WELL NO. 1	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 660' FSL & 1980' FWL of Sec. 15-T20S-R28E, Eddy Co., New Mexico		10. FIELD AND POOL, OR WILDCAT Undes. Burton Flat No.	
14. PERMIT NO.		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 15-T20S-R28E	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3241' GR		12. COUNTY OR PARISH Eddy	

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:
TEST WATER SHUT-OFF <input type="checkbox"/> FRACTURE TREAT <input type="checkbox"/> SHOOT OR ACIDIZE <input type="checkbox"/> REPAIR WELL <input type="checkbox"/> (Other) <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETE <input type="checkbox"/> ABANDON* <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/> FRACTURE TREATMENT <input type="checkbox"/> SHOOTING OR ACIDIZING <input type="checkbox"/> REPAIRING WELL <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> ABANDONMENT* <input type="checkbox"/> (Other) <input type="checkbox"/> <u>Set and cementing 5-1/2" csg.</u>
(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)		

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all marker and zones pertinent to this work.) *

T.D. 11,520' Shale and Sand. Waiting on completion unit. Drilled to a T.D. of 11,520' and ran 26 Jts. (1092.00') 5-1/2" OD 20# N-80 and 251-1/2 Jts. (10413.47') 5-1/2" OD 17# N-80 casing set and cemented @ 11,519' w/900 sacks Class H w/0.6% CFR-2 and 5# KCL/sack cement. Plug down @ 12:40 am on 2-21-75. Bumped float with 2600# - Held O.K. WOC 6 Hrs. Ran Temp. Survey. Top of cement @ 8140'.

RECEIVED

MAR - 3 1975

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED _____
BY E. Y. WILDER

TITLE Region Operation Manager

DATE February 28, 197

(This space for Federal or State office use)

APPROVED BY 150
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE

***See Instructions on Reverse Side**