

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

IN OIL COMS. 000135-77
Artesia, NM 88210
PERMIT TO DRILL
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 029588

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Harris "6"

9. WELL NO.

10. FIELD AND POOL, OR WILDCAT

Golden Lane Field

11. SEC. T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 6-21S-29E

12. COUNTY OR PARISH

Eddy

13. STATE

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR
Meadco Properties LTD

3. ADDRESS OF OPERATOR
P. O. Box 2236, Midland, Texas 79702

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface

3147' FNL & 660' FEL, Sec. 6, T-21-S, R-29-E

14. PERMIT NO.

15. ELEVATIONS (Show whether DE, RT, CR, etc.)

3469.6 Gr

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐ WELL OR ALTER CASING ☐
FRACTURE TREAT ☐ MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐ ABANDON* ☐
REPAIR WELL ☐ CHANGE PLANS ☐
(Other) ☐

WATER SHUT-OFF ☐ REPAIRING WELL ☒
FRACTURE TREATMENT ☐ ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐ ABANDONMENT* ☐
(Other) ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

5/13/83 - RUPU. Pulled tbg & found parted @ 2155'. Ran overshot. Stuck same @ 1085' & could not free. 4 1/2" csg moving up & down.
5/14/83 - Back off tbg & pull same. Pulled & layed down 2155' of 4 1/2" casing. Parted in body by corrosion.
5/15/83 - SD.
5/16/83 - Pick up 2 7/8" work string & ran flat bottom overshot. Could not catch fish. Ran 3 3/4 overshot w/cutlip guide, could not catch fish. Ran overshot w/7 1/2" cutlip guide, could not catch fish.
5/17/83 - Ran 7" flat bottom mill & started milling @ 2167'. Had 3' of fill, tagged top of csg @ 2170'. Dress 3' of csg & pulled up. Tried to go back & had 18" of fill. POOH w/mill. Mill wiped out.
5/18/83 - Ran 3 3/4" overshot w/cutlip guide. Tag fish @ 2173'. Rotate tool went down 20' on outside of 4 1/2" & possibly on outside of 8 5/8". Layed down work string & ran production 2 3/8" tbg to 2130'. RDPU. Prepare to P&A.

18. I hereby certify that the foregoing is true and correct.

SIGNED David Cotner

TITLE David Cotner - Engineer

DATE 8/30/83

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

ACCEPTED FOR RECORD

SEP 2 1983

*See Instructions on Reverse Side

ROSWell, NEW MEXICO