

YATES CHEROKEE # 1
SECTION 25,, T21S, R24E
EDDY COUNTY, NEW MEXICO

January 25, 1975 Spudded hole 0-40'
January 31, 1975 Reaming hole to 16" in lime
February 1, 1975 Reaming hole to 16" in lime 10'
Rancher said not to come back after today - Have Grace to contact him.
February 2,3,4,5,6 Kept off by Rancher
February 7, 1975 Drove around Keep Out Sign to get to work.
Reaming hole to 18'
February 8, 1975 Reaming hole.
February 9, 1975 Shut down
February 10, 1975 Drilling 41' in lime - 16 hrs.
February 11, 1975 Drilling 53' in lime - 16 hrs.
February 12, 1975 Reaming hole 12 hrs.
February 13, 1975 Reaming hole at 55'. 16 hrs.
February 14, 1975 Reaming on hole drilling to 60' in lime 16 hours
February 15, 1975 Reaming and drilling to 63 ft. in lime 12 hours
February 16, 1975 Shut down
February 17, 1975 Drilled to 73' in lime 16 hrs.
February 18, 1975 Drilled at 80' in lime 16 hrs.
February 19, 1975 Drilled to 85' in lime 12 hrs.
February 20, 1975 Reaming and straightening hole. 16 hrs.
February 21, 1975 Reaming and straightening hole. 16 hrs.
February 22, 1975 Shut down. (Snow)
February 23, 1975 Shut down.
February 24, 1975 Reaming hole 16 hrs.
February 25, 1975 Reaming hole to 90' 16 hrs.
February 26, 1975 Reaming hole at 95' 12 hrs.

RECEIVED

MAR 3 1975

O. C. C.
ARTESIA, OFFICE