

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1 ✓
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

RECEIVED

APR 2 1975

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>		4. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
2. Name of Operator Harvey E. Yates Co., Inc. ✓		5. State Oil & Gas Lease No. OG-6027
3. Address of Operator Suite 1000, Security Nat'l Bank Bldg., Roswell, N.M. 88201		7. Unit Agreement Name
4. Location of Well UNIT LETTER <u>G</u> <u>1650</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>15</u> TOWNSHIP <u>21S</u> RANGE <u>27E</u> NMPM.		8. Farm or Lease Name Cedar Hills Com
15. Elevation (Show whether DF, RT, GR, etc.) 3310 GR		9. Well No. #2
16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data		10. Field and Pool, or Wildcat Und. Burton Flat Strawn, Morrow
NOTICE OF INTENTION TO:		12. County Eddy
SUBSEQUENT REPORT OF:		

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐
OTHER ☐

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☒
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐
OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Drilled 17½" Hole to 618'. Ran 14 jts. 48#, ST&C, Range 3, H40S, casing and set at 618'. Used a Texas Pattern Shoe and automatic insert float. Cemented with 275 sx. Howco Lite, ½# Flocele per sack and 2% CaCl by volume, plus 300 sx. Class C with ¼# Flocele per sack and 2% CaCl by volume. Plug down at 8:45 P.M. 3/21/75. Did not circulate. Tagged top outside 13 3/8" at 76' from surface. Filled annular space to surface with redi-mix cement. W.O.C. 18 hrs. Tested casing with 800 psi for one hour. Tested o.k. Drilling.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Paul White

TITLE Engineer

DATE 4-1-75

APPROVED BY W. A. Gressett

TITLE SUPERVISOR, DISTRICT II

DATE APR 2 1975

CONDITIONS OF APPROVAL, IF ANY: