YATES CHERCKEE # 1-Y SECTION 25, T2L5, R2LE EDDY COUNTY, NEW MEXICO

April 25, 1975	Drilled to 135' in lime 16 hrs.	
April 26, 1975	Breaking down tools and forge dressing bit 10 hrs.	
April 27, 1975	Shut down.	
April 28, 1975	Drilled 150' in lime. 16 hrs.	
April 29, 1975	Drilled 165' in lime. 16 hrs.	
April 30, 1975	Drilled 175' in lime. 12 hrs.	
May 1, 1975	Forge dressing bit. Reamed on hole 16 hrs. (no footage)	
May 2, 1975	Reaming hole and drilling 180' in lime 16 hrs.	
May 3, 1975	Reaming hole and drilling 183' in lime 16 hrs.	
May L, 1975	Shut down.	
May 5, 1975	Reaming 16 hrs.	
May 6, 1975	Reaming 12 hrs.	RECEIVED
May 7, 1975	Reaming 16 hrs.	RECEIVED
May 8, 1975	Reaming at 190'.	MAY 2 6 1975
May 9, 1975 ·	Drilled 190' to 200' in lime. 12 hours	
May 10, 1975	Forge dressing bits. 4 hours.	
May 11, 1975	Shut down.	
May 12, 1975	Reaming at 210' in lime 16 hrs.	
May 13, 1975	Reaming at 235'. 16hrs.	
May 14, 1975	Reaming 12 hrs.	
May 15, 1975	Reaming to make hole 18" 16 hrs.	
May 16, 1975	Reaming to 18* hole 16 hrs.	
May 17, 1975	Reaming at 210' 12 hrs.	
May 18, 1975	Forge dressing bits 8 hrs.	
May 19, 1975	Almost at bottom reaming 16 hrs.	
May 20, 1975	Reamed at 250' 18" hole in lime 16 hrs.	
May 21, 1975	Forge dressing bit, drilled to 265' lime, 16	hrs.

53