

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPL  
(Other instructions  
reverse side)E-  
re-Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 12211-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Little Box Canyon Unit

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Wildcat Morrow

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 7-T21S-R22E

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR  
Cities Service Oil Company

3. ADDRESS OF OPERATOR  
Box 1919 - Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface  
1650'FSL & 1980'FEL of Sec. 7-T21S-R22E, Eddy Co., New Mexico

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)  
4465' GR(Est.)

RECEIVED

AUG 20 1975

O. C. C.  
ARTESIA OFFICE

## 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON\*

REPAIR WELL

CHANGE PLANS

(Other)

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT\*

(Other)

Set and cementing 5-1/2" csg. x

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

T.D. 8350' Lime, Shale and Sand. Waiting on completion unit. Drilled to a T.D. of 8350' and ran 25 Jts. (1057.19') 5-1/2" OD 17# N-80, 44 Jts. (1851.83') 5-1/2" OD 17# K-55 and 137-1/2" Jts. (5390.87') 5-1/2" OD 15.5# K-55 casing set and cemented @ 8314' (could not get to T.D. w/csg.) w/560 sacks Class H w/0.5% BJ friction reducer and 1% KCl cement. Plug down @ 4:37 PM on 8-12-75. Bumped float w/1900# - Held O.K. WOC 16 hrs. Ran Temp. Survey. Top of cement @ 5750'.

RECEIVED  
AUG 18 1975  
U. S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Region Operation Manager

DATE August 14, 1975

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side