

DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

on re-

5. LEASE DESIGNATION AND SERIAL NO.

NM 04219

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. GIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR MONSANTO COMPANY		8. FARM OR LEASE NAME HONDO FEDERAL	
3. ADDRESS OF OPERATOR 321 West Texas, Midland, Texas 79701		9. WELL NO. 1	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1980' FNL & 660' FWL of Section 14		10. FIELD AND POOL, OR WILDCAT Wildcat	
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 14, T-20S, R-26E		12. COUNTY OR PARISH Eddy	
13. STATE New Mexico		14. PERMIT NO.	
15. ELEVATIONS (Show whether DF, RT, CR, etc.) 3301 Gr.; 3318 DF		16. COUNTY OR PARISH Eddy	

RECEIVED

SEP 19 1975

U.S.G. ARTESIA, OFFICE

10. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Drilled 8 3/4" hole to 10,285'; Well was plugged & abandoned as follows:  
Setting Plugs @:

- #1 9800-9650; 150'; 55 Sx.
- #2 8300-8150; 150'; 55 Sx.
- #3 6600-6450; 150'; 55 Sx.
- #4 5000-4850; 150'; 55 Sx.
- #5 3300-3150; 150'; 55 Sx.
- #6 1925-1825; 100'; 40 Sx.
- #7 20- 0; 20'; 10 Sx.

Total 325 Sx. Class "H" Cmt.

Job complete 8:00 AM 9/5/75; Hole between plugs was filled w/ better than 25% Gel per Bbl. Wtr; 4" dry hole marker set at surface w/ location marked thereon.

You will be notified when location is cleaned up and ready for inspection.

RECEIVED

SEP 12 1975

U. S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Regional Production Mgr.

DATE 9/11/75

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side

postcard ID-2  
11-275 9-26-75