

NEW MEXICO OIL CONSERVATION COMMISSION

RECEIVED

JUL 31 1975

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)

ARTESIA, OFFICE

5a. Indicate Type of Well State <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Oil <input type="checkbox"/> Other <input type="checkbox"/>
5. State Oil & Gas Lease No. K-5115
7. Unit Agreement No.
8. Farm or Lease Name Stonewall "EP" State
9. Well No. 1
10. Field, Pool, or Well Unit Wildcat Morrow
12. County Eddy

1. Name of Operator Yates Petroleum Corporation ✓
3. Address of Operator 207 South 4th Street - Artesia, NM 88210
4. Location of Well UNIT LETTER F 1980 FEET FROM THE North LINE AND 1980 FEET FROM THE West LINE, SECTION 30 TOWNSHIP 20S RANGE 28E NMPM.

15. Elevation (Show whether DF, RT, GP, etc.)
3282' GR

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐
OTHER ☐

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☒
OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated completion date if proposed work) SEE RULE 1103.

TD 2800'. Ran 10 joints of 8-5/8" 32#, K-55 (421') and 60 jts of 8-5/8" 24#, K-55 (2420') (total 2841') set at 2799' KB w/guide shoe, float collar at 2758', 3 centralizers at 2758, 2677 and 1357', baskets at 1398, 1316'. Cemented w/920 sacks of Hali-lite w/5% gilsonite, 1/2% flocele, 2% CaCl and 200 sacks Class C w/2% CaCl. PD 2:10 PM 7-26-75. Cement did not circ. WOC 5 1/2 hours and ran Temp. Survey, found top of cement at 1550'. Ran 1" to 1225'. Spotted 75 sacks Class C 3% CaCl. PD 11:45 PM 7-26-75. WOC 4 hours and ran 1" to 1225'-no fill up. Spotted 35 sacks of Class C 3% CaCl. PD 5:15 AM 7-27-75. Ran 1" to 1225'. Spotted 50 sacks of Class C 3% CaCl. PD 9:00 AM 7-27-75. Lost 7 jts of 1" - no fill - dumped 1 yard of pea gravel down 8-5/8" & 13-3/8" annulus. Tagged top at 982'. Ran 1" to 982' and spotted 75 sacks Class C 3% CaCl. Had returns. PD 3:40 PM 7-27-75. Ran 1" and tagged cement top at 734'. Spotted 75 sacks of Class C 3% CaCl w/full returns. PD 8:15 PM 7-27-75. Hole stood full of fluid. Ran 1" and tagged top of cement at 629', spotted 220 sacks Class C 3% CaCl. Cmt. Circ. PD 10:30 PM 7-27-75. WOC 53 hrs. NU, BOP's (installed) press tstd BOP & csg to 1500# for 30". OK. Drld plg & tstd to 600#, ok. Redcd hole to

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.
7-1/8" and resumed drilling.

SIGNED Eddie J. Gressett TITLE Engineer DATE 7-30-75
APPROVED BY W. A. Gressett TITLE SUPERVISOR, DISTRICT #7 DATE AUG 4 1975
CONDITIONS OF APPROVAL, IF ANY: