

(May 1963)

DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

(Other instructions on reverse side)

Budget Bureau No. 42 K1424.  
6. LEASE DESIGNATION AND SERIAL NO.

LC 072015-C

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

MARALO, INC.

3. ADDRESS OF OPERATOR

P. O. Box 832, Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface

1980' FNL & 1980' FEL, Section 33, T-20-S, R-27-E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3195 Gr.

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Hanson Federal

9. WELL NO.

3

10. FIELD AND POOL, OR WILDCAT

North Avalon

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 33, T-20-S, R-27-E

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON\*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Well spudded 8:00 a.m. July 31, 1975. Set 373' of 13-3/8" 48#

H-40 ST&C surface casing with 425 sxs Class "C" cement. Did not circulate. On 8/2/75 finished cementing thru 1" pipe w/300 sxs Class "C" cement & 4% calc. chlor. Ran Temperature Survey - Top of cement at 140'. After 24 hours pipe tested with 1000# pressure for 30 minutes. Pipe tested okay.

RECEIVED

AUG 14 1975

O. C. C.  
ARTESIA, OFFICE

RECEIVED

AUG 12 1975  
U. S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Production Clerk

DATE August 11, 1975.

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

\*See Instructions on Reverse Side