

(May 1983)

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR MARALO, INC. ✓		8. FARM OR LEASE NAME Hanson Federal	
3. ADDRESS OF OPERATOR P. O. Box 832, Midland, Texas 79701		9. WELL NO. 3	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1980' FNL & 1980' FEL, Section 33, T-20-S, R-27-E		10. FIELD AND POOL, OR WILDCAT North Avalon	
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3195 Gr.	
12. COUNTY OR PARISH Eddy		13. STATE New Mexico	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input checked="" type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	(Other) <input type="checkbox"/>

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

On August 5, 1975, ran 8-5/8" 28# K ST&C casing. Set at 2302'; cemented with 900 sxs Halliburton Lite Wate, 5# Gil, 1/2# Flocele; 200 sxs Class "C" wtih 2% CC. Plug down at 7:00 a.m. August 6, 1975. Cement circulated. After 24 hours pipe tested with 1500# pressure for 30 minutes. Pipe tested okay.

RECEIVED  
AUG 12 1975  
U.S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

*Francis J. Vanum*

TITLE Production Clerk

DATE August 11, 1975

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

\*See Instructions on Reverse Side

APPROVED  
AUG 12 1975  
*A. J. B. B. B.*