

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPlicate
(Other instructions on reverse side)Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> Dry Hole		5. LEASE DESIGNATION AND SERIAL NO. NM 26824 - Copy to 137	
2. NAME OF OPERATOR Cities Service Oil Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR Box 1919 - Midland, Texas 79701		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1980'FNL & 860'FWL of Sec. 17-T21S-R22E, Eddy Co., New Mexico		8. FARM OR LEASE NAME Loafer Draw B	
14. PERMIT NO.		9. WELL NO. 1	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4503' GR		10. FIELD AND POOL, OR WILDCAT Wildcat - Morrow	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 17-T21S-R22E	
		12. COUNTY OR PARISH Eddy	
		13. STATE New Mexico	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

T.D. 8591' Shale. This well was plugged and abandoned in the following manner:

1. Spotted a 50 sack cement plug across top of Morrow @ 8175 - 8025'.
2. Spotted a 50 sack cement plug across top of Strawn @ 7560 - 7410'.
3. Spotted a 50 sack cement plug across top of Wolfcamp @ 5150 - 5000'.
4. Spotted a 35 sack cement plug across top of Abo @ 3690 - 3590'.
5. Spotted a 35 sack cement plug across top of Tubb @ 3100 - 3000'.
6. Spotted a 35 sack cement plug @ 1850 - 1750' (1/2 in and 1/2 out of 8-5/8" casing seat @ 1800').
7. Spotted a 10 sack cement surface plug @ 50 - 0' and installed a 4" dry hole marker extending 4' above the ground to designate a plugged and abandoned location.

USGS was notified and witnessed the plugging of this well.

RECEIVED

FEB 2 1976

MAR 16 1976

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct.

SIGNED

ARTESIA, OFFICE

TITLE Region Operation Manager

DATE January 28, 1976

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE