

(May 1965)

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

(Other Instruct
verse side)

on re-

Copy 12-15
Form approved
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 12388-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Flanigan-Fed. Comm

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Rocky Arroyo Wolfcamp

11. SEC., T., R., OR BLK. AND
SURVEY OR AREA

Sec. 9-T22SR22E

12. COUNTY OR PARISH

Eddy

13. STATE

N.M.

1.

OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

Summit Energy, Inc.

3. ADDRESS OF OPERATOR

112 N. First, Artesia, New Mexico 88210, D.C.

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)

At surface

2080' FSL and 1980" FWL Unit (K)

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4386.6 GR

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐

(Other)

PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐

(Other)

REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

TP 6213 R+ A 4-27-76

Summit Energy, Inc., plugged and abandoned subject well by spotting 100 ft. cement plug from 4700-4600; 100 ft. cement plug from 3150-3050; 100 ft. cement plug from 1803-1703 (in and out of 8 5/8" csg. at 1803). A 10 sx. cement plug was placed in top of 8 5/8" casing with a properly identified 4"x5' pipe marker. Location will be graded and cleaned as soon as pits dry up.

RECEIVED

MAY - 3 1976

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Division Engineer

DATE

4/30/76

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side