

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)Form approved
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER		5. LEASE DESIGNATION AND SERIAL NO. NM 0354232	
2. NAME OF OPERATOR Cities Service Oil Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR P. O. Box 1919 - Midland, Texas		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 660' FSL, 1980' FWL of Section 20, T-21-S, R-27-E, Eddy County, New Mexico.		8. FARM OR LEASE NAME Elizondo Federal A	
		9. WELL NO. 3	
		10. FIELD AND POOL, OR WILDCAT Und. Burton Flat Morrow	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Section 20, T-21-S, R-27-E	
14. PERMIT NO. DEC 7 1976	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3183' GR	12. COUNTY OR PARISH Eddy	13. STATE New Mexico

RECEIVED

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

O. C. C. NOTICE OF INTENTION TO:

ARTESIA, OFFICE

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

T.D. 600'. Anhydrite. Prep to drill ahead. This well was spudded 11/20/76 and drilled to a T.D. of 600'. Ran 14 joints (539.18') of 13-3/8" OD 48# K55 8R ST&C casing set at 600' with 300 sacks thick set w/10# Gilsonite/sack, 1/4# Flocele, 3% CaCl₂ and 325 sacks Class C w/2% CaCl₂. Bumped plug w/1000# - held OK. WOC 12 hours. Cement did not circulate. Ran Temp. Survey. Top of cement @ 240'. Used 4 cement baskets @ 525', 484', 442' & 399'. Ran 1" in annulus to 127'. Cemented annulus with 450 sacks Class C w/3% CaCl & 10 yards of pea gravel. Cement circulated. Job complete 1630 MST, 11/22/76. NU casinghead & BOP to 1100#/30 mins. - OK.

U.S.G.S. notified but did not witness job.

RECEIVED

DEC 1 1976

U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Region Operations Manager

DATE 11/29/76

(This space for Federal or State office use)

APPROVED BY

TITLE ACTING DISTRICT ENGINEER

DATE DEC 6 1976

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side