

UNITED STATES OF AMERICA  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYCopy to SF  
Form approved.  
Budget Bureau No. 42 R1424.

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	5. LEASE DESIGNATION AND SERIAL NO. NM 03677
2. NAME OF OPERATOR Yates Petroleum Corporation	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR 207 South 4th Street - Artesia, NM 88210	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' FNL & 1980' FEL of Section 20-20S-29E	8. FARM OR LEASE NAME Stebbins "GQ" Com
14. PERMIT NO. DEC 20 1976	9. WELL NO. 1
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3261' GR	10. FIELD AND POOL OR WILDCAT Undesignated
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 20-20S-29E Unit B NMPM
	12. COUNTY OR PARISH Eddy
	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data			
O. C. C. ARTESIA, OFFICE		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDONMENT*
REPAIR WELL	CHANGE PLANS	(Other) Spud	
(Other)			

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Spudded a 17½" hole at 8:00 AM 10-28-76.

TD 605' - Ran 14 joints of 13-3/8" 48# H-40 ST&C (627.07') of casing set at 605' KB. Cemented by Halliburton w/450 sacks of Lite 5# gilsonite, 1/2# flocele, 4% CaCl, followed w/150 sacks of Class C 4% CaCl. PD 5:15 AM 10-29-76. Cement did not circulate. Top of cement at 280'. Filled hole w/46 yards of Ready-Mix. WOC 18 hours, nipples up, tested BOP's to 800#, OK. Reduced hole to 12¼", cut off casing, drilled plug and resumed drilling.

RECEIVED

DEC 15 1976

U.S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

*Christine J. Lemaire*

TITLE

Geol. Secty

DATE

12-15-76

(This space for Federal or State office use)

APPROVED BY

*Joe J. Lara*

TITLE

ACTING DISTRICT ENGINEER

DATE

DEC 17 1976

CONDITIONS OF APPROVAL, IF ANY: