

N. M. U. S. STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRI
(Other instruction
verse side)ATE*
- reForm approved.
Budget Bureau No. 42 R1424.
5. LEASE DESIGNATION AND SERIAL NO

NM 886-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

El Paso Federal "SS"

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Undesignated

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREASec. 11-21S-21E
Unit J NMP1

12. COUNTY OR PARISH

Eddy

13. STATE

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back or
Use "APPLICATION FOR PERMIT--" for such proposals.)1. OIL WELL ☐ GAS WELL ☒ OTHER

JAN 18 1977

2. NAME OF OPERATOR

Yates Petroleum Corporation

3. ADDRESS OF OPERATOR

ARTESIA, OFFICE

207 South 4th Street - Artesia, NM 88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1930' FSL & 2080' FEL of Section 11-21S-21E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4556' GR

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Plug Back & set Prod Csg

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones parti-
nent to this work.)*

TD 8458'; PBTD 7180' by wireline. WIH open ended and spotted 50 sacks of Class H cement at 7750-7600'; 30 sacks of Class H cement at 7350-7250'. Layed down drill pipe and drill collars and/203 joints of 5 1/2" 15.5# K-55 LT&C (7266') of casing set at 7244'. Cemented w/250 gallons of mud flush, 100 sacks of Halli-Lite w/5# gilsonite, 1/4# flocele, 5# salt/sx, 150 sacks of Class C w/0.5# CFR2 and 5# salt, 150 sacks of Class C w/0.5# CFR2, 1/4# flocele and 5# salt. PD 11:00 AM 1-9-77. WOC. Set slips backed off landing joint. Tested casing to 1500#. OK. Ran Temperature Survey and found top of cement outside of casing at 5810'. PBTD 7180' by wireline.

RECEIVED

JAN 17 1977

U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Geol. Secty

DATE 1-16-77

(This space for Federal or State office use)

APPROVED BY

TITLE ACTING DISTRICT ENGINEER

DATE JAN 17 1977

CONDITIONS OF APPROVAL, IF ANY: