

UNITED STATES **N. M. O. C. C. COPY** IN TRIPLICATE*
DEPARTMENT OF THE INTERIOR (Other instructions on reverse side)
GEOLOGICAL SURVEY

Form approved,
Budget Bureau No. 42-R0424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR Yates Petroleum Corporation		8. FARM OR LEASE NAME NW Indian Basin Unit	
3. ADDRESS OF OPERATOR 207 South 4th Street - Artesia, NM 88210		9. WELL NO. 1	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1885' FSL & 2080' FWL of Sec. 12-21S-22E		10. FIELD AND POOL, OR WILDCAT Undesignated	
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 12-21S-22E Unit K NMPM		12. COUNTY OR PARISH Eddy	
13. STATE NM		14. PERMIT NO.	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4107' GR		16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data	

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input checked="" type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) Spud	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*
Spudded a 17½" hole at 8:30 PM 12-4-76.

RECEIVED

DEC 22 1976

**U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO**

18. I hereby certify that the foregoing is true and correct

SIGNED Christine Ambrose	TITLE Lead Deputy	DATE 12-21-76
(This space for Federal or State office use)		
APPROVED BY Lee S. Lam	TITLE ACTING DISTRICT ENGINEER	DATE DEC 23 1976
CONDITIONS OF APPROVAL, IF ANY:		

1900

1901

1902

1903

1904

1905