

Yates Petroleum Corporation
Box Canyon Unit - NM 886
Sec. 13-21S-21E
Eddy Co., NM (Cont'd)

6:15 AM 1-18-77. Cement 60' from surface. WOC filled hole w/3 yards of Ready-Mix. WOC 48 hours. Nippled up, installed BOP's and tested to 1500#. OK. Reduced hole to 7-7/8" drilled plug and tested to 600#. OK. Resumed drilling.