

N. M. O. C. C. COPY
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

copy to SF
Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.
NM 0553785-A
6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER		MAR 28 1977	
2. NAME OF OPERATOR Cities Service Oil Company		D. C. C.	
3. ADDRESS OF OPERATOR P. O. Box 1919, Midland, Texas 79702		ARTESIA, OFFICE	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 2310' FNL, 660' FWL of Sec. 27, T-21-S, R-27-E, Eddy County, New Mexico			
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3217.2' GR		9. WELL NO. 2
		10. FIELD AND POOL, OR WILDCAT Und. La Huerta Morrow	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 27, T21S, R27E
		12. COUNTY OR PARISH Eddy	13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input checked="" type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

T.D. 602'. Red Bed and anhydrite. Prep. to drill ahead. This well was spudded on 3/12/77. Set 15 joints (579.2') of 13-3/8" OD, 54.5#, K55 ST&C casing at 602' and cemented with 200 sacks Class C thick set w/10# Gilsonite, 1/4# Flocele, and 2% CaCl₂ and 500 sacks Class C with 2% CaCl₂. Plug down at 11:45 P.M., 3/13/77. Landed plug w/800# - held ok. Circ. 80 sacks to pit. Tested casing & BOP to 500# - ok.

Mr. James Brafield with U.S.G.S. witnessed job.

RECEIVED
MAR 24 1977
U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED <u>[Signature]</u>	TITLE <u>Region Operations Manager</u>	DATE <u>March 22, 1977</u>
(This space for Federal or State office use)		
APPROVED BY <u>[Signature]</u>	TITLE <u>ACTING DISTRICT ENGINEER</u>	DATE <u>MAR 25 1977</u>
CONDITIONS OF APPROVAL, IF ANY:		