

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRII
(Other Instruction
verse side)DATE
n recopy to SF
Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

0354232

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Elizondo Federal

9. WELL NO.

5

10. FIELD AND POOL, OR WILDCAT

Und. Burton Flat Morrow

11. SEC., T., R., M., OR BLK. AND
SURVEY OF AREA

Sec. 34, T-21S, R-27E

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

1. OIL WELL ☐ GAS WELL ☒ OTHER

RECEIVED

2. NAME OF OPERATOR

Cities Service Oil Company

MAY 11 1977

3. ADDRESS OF OPERATOR

P. O. Box 1919, Midland, Texas 79702

4. LOCATION OF WELL (Report location clearly and in accordance with any State regulations.)

See also space 17 below.)
At surface1780' FSL, 2180' FWL, of Sec. 34, T21S, R27E, Eddy
County, New Mexico.

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, OR, etc.)

3142.9' GR

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

T.D. 605' Surf. rock & Anhy. Prep. to drill ahead.

This well was spudded on April 29, 1977, & drilled to 605'. Set 15 joints (582.2') of 13-3/8" OD, 54.5#, 8R, K55, ST&C casing at 605' & cemented with 600 sx Class C w/2% CaCl. Bumped plug with 550# - ok. Plug down at 0350 MDT, 4/30/77. Cement did not circulate. WOC 8 hours. TOC 130'.

Ran 1" in annulus. Tagged at 124'. Cemented with 250 sx Class C w/2% CaCl. Circ. 10 sx to pit. Tested 13-3/8" to 500# - ok.

U.S.G.S. notified but did not witness.

RECEIVED

MAY 10 1977

U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Region Oper. Manager

DATE 5/5/77

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE ACTING DISTRICT ENGINEER

DATE

MAY 11 1977