

See Information for agents

EQUIPMENT & HOLE DATA

Type Test	M. F. E. OPEN HOLE		
Formation Tested	MORROW		
Elevation	-		Ft.
Net Productive Interval	11		Ft.
Estimated Porosity	-		%
All Depths Measured From	ROTARY DERRICK BUSHING		
Total Depth	10764		Ft.
Main Hole/Casing Size	8.75"		
Rot Hole/Liner Size	-		
Drill Collar Length	655'	I.D.	2.25"
Drill Pipe Length	10022'	I.D.	3.826"
Packer Depth(s)	10712 & 10718		Ft.

Sampler Pressure _____ P.S.I.G. at Surface

Recovery: Cu. Ft. Gas _____

cc. Oil _____

cc. Water _____

cc. Mud _____

Tot. Liquid cc. _____

Gravity _____ °API @ _____ °F.

Gas/Oil Ratio _____ cu. ft./bbl.

CHLORIDE CONTENT

Recovery Water _____ @ _____ °F. _____ ppm

Recovery Mud _____ @ _____ °F. _____

Recovery Mud Filtrate _____ @ _____ °F. _____ ppm

Mud Pit Sample _____ @ _____ °F. _____

Mud Pit Sample Filtrate _____ @ _____ °F. _____ ppm

Mud Type	POLEYMER	Wt.	9.9	
Viscosity	34	Water Loss	4.6	C.C.
Resist. of Mud	- @ -	*F, of Filtrate	- @ -	*F
Chloride Content	-			PPM

[illegible]

Remarks: UNSUCCESSFUL TEST. "TELEFLOW TEST SYSTEM"

Address 14TH FLOOR; MIDLAND NATIONAL BANK BUILDING; MIDLAND, TEXAS 79701

Company LARIO OIL & GAS COMPANY

Field WILD CAT

Company	STATE "F" #1	Location
Well		

Date 4-3-77

County EDDY State NEW MEXICO

Field Report No. 06201 D

County FOWLER (ODESSA) State MR. LEBOW
Technician Test Approved By

No. Reports Requested 13 (5x)