

NMOCC COPY

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATE*
(Other instructions on reverse side)Form Approved
Budget Bureau No. 42-11424

5. LEASE DESIGNATION AND SERIAL NO.

NM-0553785

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

RECEIVED

1. ☐ OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

Cities Service Company

MAY 22 1978

3. ADDRESS OF OPERATOR

P.O. Box 1919 Midland, TX 79702

O. C. C.
ARTESIA, OFFICE4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface2310' FSL, 1980' FEL, Section 27, T-21-S, R-27-E,
Eddy County, New Mexico

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Government AE

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Und. ~~Barro~~ Morrow11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 27, T-21-S, R-27-E

14. PERMIT NO.

15. ELEVATIONS (Show whether DE, RT, GR, etc.)

3181.5' GR

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

T.D. 620' Anhydrite.

This well was spudded at 1100 hrs MST, May 10, 1978, and drilled to a total depth of 620'. Ran 13-1/2 joints (597.31') of 13-3/8 OD 48#, H40, 8R, ST&C Casing set at 620', and cemented with 100 sx thickset W/10# Gilsontite, 1/4# FS, and 2% CaCl₂, followed by 650 sx Class C W/2% CaCl₂. PD at 4:45 AM MST, 5-13-78. Bumped float with 600# - OK. Cement circulated. WOC 12 hrs. Test 13-3/8" casing to 500#/30 Mins. Held OK.

USGS notified but did not witness job.

RECEIVED
MAY 19 1978
U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

E. J. Miller

TITLE

Region Operations Manager

DATE

5-16-78

(This space for Federal or State office use)

APPROVED BY

Joe D. Lara

TITLE

ACTING DISTRICT ENGINEER

DATE

MAY 19 1978

CONDITIONS OF APPROVAL, IF ANY: