Oil Conservation Commission State of New Mexico Artesia, New Mexico Page 2

> DST #2, from 11366' to 11683'; no water blanket; Took 10 min. preflow;120 min. ISIP; 150 min. FFP; 540 min. FSIP; DP recovery - reversed out - had no indication of anything but gas in DP; Sample Chamber: 4.3 cu. ft. gas @ 500 psi - no water; Pressures as follows:

> > IFP 716 - 629 ISIP 5039 FFP 811 - 1360 FSIP 5190 IH & FH 5931

BHT 1900 F

In addition, we are enclosing Sundry Notice Report on the well which reflects all perforations and bridge plug. We have also requested on the above mentioned form that the perforation indicated on C-122 be corrected to read 115294 -= 11559'. In the event something further is needed to complete your file please advise.

11483-561

Yours very truly, C & K PETROLEUM, INC.

RÊĈÊIVED SEP 9 1977 D. E. Cooper

ARTESIA, OFFICE

Administrative Supervisor

DEC:jh

Enclosure