

MOOG COPY.

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE*
(Other Instructions
verse side)

copy to SF
FORM APPROVED
Budget Bureau No. 42 R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-886

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐

RECEIVED

2. NAME OF OPERATOR
Cities Service Company

OCT 3 1977

3. ADDRESS OF OPERATOR
P. O. Box 1919, Midland, TX 79702

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

O. C. C.
ARTESIA OFFICE

660' FSL, 1980' FRL of Section 12, T-21S, R-21E,
Eddy County, New Mexico

7. UNIT AGREEMENT NAME

Little Box Canyon Unit

8. FARM OR LEASE NAME

9. WELL NO.

10. FIELD AND POOL, OR WILDCAT

Little Box Canyon-Morrow

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec 12, T-21S, R-21E

14. PERMIT NO.

15. ELEVATIONS (Show whether DE, RT, GR, etc.)

1477.67' GR

12. COUNTY OR PARISH

13. STATE

Eddy

New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETION

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☒

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

T.D. 8370', shale & lime.

Drilled to a total depth of 8370'. Ran 31 joints (1297.57') of 5 1/2" 17#, 8R, N80, ST & C casing, 49 joints (1503.13') of 5 1/2" 15.5#, 8R, K-55, ST & C casing, and 138 joints (5495.87') of 5 1/2" 15.5#, 8R, K-55, LT & C casing set at 8317.69' and cemented with 625 sacks Class H w/0.5% CFR-2 & 5# KCL/sack. Plug down at 2:45 MDT, 9/18/77. Bumped float with 2000#-OK. WOC 20 hours. Ran temperature survey. Top of cement 5990'.

RECEIVED

SEP 28 1977

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Region Operation Manager

DATE

Sept. 27, 1977

(This space for Federal or State office use)

APPROVED BY

TITLE

ACTING DISTRICT ENGINEER

DATE

SEP 29 1977

*See Instructions on Reverse Side