

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on
reverse side)Form Approved
Budget Bureau No. 42-01424

5. LEASE DENIGATION AND REPEAL NO.

NM-12241-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. ☐ OIL WELL ☐ GAS WELL ☒ OTHER	NOV 14 1977	7. UNIT AGREEMENT NAME Little Box Canyon Unit
2. NAME OF OPERATOR Cities Service Company	C. S. Co.	8. FARM OR LEASE NAME
3. ADDRESS OF OPERATOR P.O. Box 1919 Midland, TX 79702	ARTESIA, N.M.	9. WELL NO. 3
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 660 FNL, 1980' FEL of Section 7, T-21S, R-22E Eddy County, New Mexico		10. FIELD AND POOL, OR WILDCAT Little Box Canyon (Morrow)
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 7, T-21S, R-22E
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4375' GR	12. COUNTY OR PARISH Eddy
		13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETION

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

T.D. 8390', shale and lime.

Drilled to a total depth of 8390'. Ran 35 Joints (1464.44') of 5-1/2" OD 17#, N-80, 8R, ST&C Casing, 63 Joints (2299.69') of 5-1/2 OD, 15.5#, K55, 8R, LP&C Casing and 126 Joints (4453.47') of 5-1/2" OD, 14#, K55, 8R, ST&C Casing set at 8240.45' and cemented with 800 sacks Class H W/0.5% CFR-2 and 5# KCL/sx. Plug down at 1155 MDT, 10/28/77. Bumped plug with 2600#-OK. WOC 8 hours. Ran temperature survey. Top of cement 5410'.

RECEIVED
NOV 7 1977
U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

E. Spaulder

TITLE Region Operations Manager

DATE November 3, 1977

(This space for Federal or State office use)

APPROVED BY

Lee S. Lara

TITLE ACTING DISTRICT ENGINEER

DATE NOV 10 1977

CONDITIONS OF APPROVAL, IF ANY: