

10. Plans for Restoration of Surface:

- A. After completion of drilling and/or completion operations, all equipment and other material not needed for operations will be removed. Pits will be filled and location cleaned of all trash and junk to leave wellsite is as aesthetically pleasing condition as possible.
- B. Any ungraded pits containing fluids will be fenced until they are filled.
- C. After abandonment, any special rehabilitation and/or revegetation requirements of surface management agency will be complied with and accomplished as expeditiously as possible. All pits should be filled and levelled within 90 days after abandonment.

11. Other Information:

- A. Topography: Wellsite is located on the south slope of Angel Draw.
- B. Soil: Soil is sandy loam underlain by caliche.
- C. Flora and Fauna: Vegetative cover is generally perennial native range grasses with a few mesquite and greasewood brush. Wild life in area is that typical of semi-arid desert land and includes coyotes, rabbits, rodents, reptiles and birds.
- D. Ponds and Streams: There are no rivers, streams, lakes or ponds in the immediate area.
- E. Residences and Other Structures: Nearest occupied dwelling is the Angell Ranch house approximately two miles northeast of proposed location.
- F. Land Use: Land is used for cattle grazing.
- G. Surface Ownership: Wellsite is on Federal surface.

12. Operator's Representative:

Gulf Energy and Minerals Co. - U. S.
A Division of Gulf Oil Corporation
P. O. Box 670, Hobbs, N. M. 88240
Telephone No. 505/393-4121
Area Production Manager: C. D. Borland.