TITL' J.D. COPY

6/3	SF
1	58° v 1

ł.

Form 1 -331 Doi: 1.973	Form Approved. Budget Bureau No. 42-R1424
UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	NM_13968 6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)	8. FARM OR LEASE NAME
1. oil ca gas	Huber IA Federal
well well other Dry Hole	9. WELL NO.
2. NAME OF OPERATOR	1
Yates Petroleum Corporation 🗸	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Wildcat (Box Canyon Area)
207 So. 4th St., Artesia, NM 88210	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) 1880' FNL & 1980' FEL, Sec. 15-215-21E	Sec. 15-T21S-R21E
AT SURFACE: AT TOP PROD. INTERVAL:	12. COUNTY OR PARISH 13. STATE Eddy NM
AT TOTAL DEPTH:	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 4672' GR, 4682' KB
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	(NOTE: Report results of multiple completion or zone change on Form 9–330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, ncluding estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Surface restoration as been completed as per	
Remove caliche, recontour and reseed.	RECEIVED RECEIVED U.S. GLULUSIUNIL SUNNLY ARTESIA, NEW MEXICO
	REC 1990
	HEULUSIUM MEXICO
	U.S. ARTESIA
Subsurface Safety Valve: Manu. and Type	Set @ Ft.
18. Thereby certify that the foregoing is true and correct	
SIGNED UDEN Half TITLE Engineer	DATE Sept. 29, 1980
(Orig. Sgd.) PLILL W. CHESTER TITLE	्त DATE CCT २ २ 1980

CONDITIONS OF APPROVAL, 1F ANY: