

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLI
(Other instructions
reverse side)

UB
re

Form approved.
Budget Bureau No. 42-R1424

5. LEASE DESIGNATION AND SERIAL NO.

NM 13968

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Huber IA Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Wildcat (Box Canyon Area)

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 15, T21S, R21E

12. COUNTY OR PARISH 13. STATE

Eddy

NM

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ Dry Hole

2. NAME OF OPERATOR

Yates Petroleum Corporation

3. ADDRESS OF OPERATOR

207 South 4th Street, Artesia, New Mexico 88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)

At surface

1880' FNL & 1980' FEL, Section 15, T21S, R21E, NMPM

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4672' GR, 4682' KB

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☒

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

This well has been plugged as follows:

RIH with tubing and displaced hole with heavy mud
Spotted 40 sack Class "C" plug through tubing @4400'
Spotted 15 sack Class "C" plug through tubing @3560'
Spotted 15 sack Class "C" plug through tubing @2330'
Found 4½" casing freepoint @1814' - Cut and recovered 1794' of 4½" casing
Spotted 35 sack Class "C" plug through tubing across 4½" casing stub @ 1820'
Spotted 40 sack Class "C" plug through tubing across 8 5/8" casing shoe (1324') @1381'
Spotted 5 sack Class "C" plug at surface
Installed regulation abandonment marker.

Surface restoration has not been completed but will be accomplished in near future.

18. I hereby certify that the foregoing is true and correct

SIGNED

Albert R. Hall

TITLE

Engineer

DATE May 21, 1980

(This space for Federal or State office use)

APPROVED (Orig. Sgd.) PETER W. CHESTER

TITLE

SEALING DISTRICT ENGINEER

DATE OCT 21 1980

CONDITIONS OF APPROVAL, IF ANY: