

XEROX COPY

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPlicate  
(Other instructions on  
reverse side)Form approved  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-0553785

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Baumgartner Fed. Com.

9. WELL NO.

1

10. FIELD AND POOL OR WILDCAT

Und. ~~Burton Flat~~ Morrow11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

26-21-27

12. COUNTY OR PARISH

Eddy

13. STATE

NM

1. OIL ☐ GAS ☒ OTHER ☐  
WELL WELL

2. NAME OF OPERATOR

Amoco Production Company

3. ADDRESS OF OPERATOR

P. O. Drawer A, Levelland, Texas 79336

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)

At surface

1980' FSL x 660' FWL (Unit L, Sec 26)

14. PERMIT NO.

15. ELEVATIONS (Show whether IF, RT, GR, etc.)

3188.9 GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON\* ☐CHANGE PLANS ☐

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☒FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) Set Salt String ☒REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT\* ☐(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*

Reached TD of 3000' on 12-12-77. Run 8-5/8" casing and set at 3000'. Cement with 1600 sx Class C cement and additives. Plug down at 2:45 P.M. 12-12-77. Cement did not circulate. Ran temperature survey and found top of cement at 930'. Cement with 480 sx cement and circulate 5 sx. Test casing with 1000# for 30 minutes. Test ok. Reduce hole to 7-7/8" and resume drilling.

RECEIVED  
DEC 19 1977  
U.S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED Randy AtkinsTITLE Staff Assistant (SG)DATE 12-16-77

(This space for Federal or State office use)

APPROVED BY [Signature]TITLE ACCOMPLISHED ENGINEERDATE DEC 20 1977

CONDITIONS OF APPROVAL, IF ANY:

0 & 4-USGS-ART  
1-Div.  
1-Susp.  
1-RC  
1-Monsanto  
1-Champlin

\*See Instructions on Reverse Side