

NMOCC COPY

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPL
(Other instructions
reverse side)E*
re-

Copy to SF

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 9187

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Box Canyon "4A"

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Undesignated

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA Unit B NMPM
Sec. 23-21S-21E

12. COUNTY OR PARISH 13. STATE

Eddy

NM

1. OIL ☐ GAS ☒ OTHER ☐

2. NAME OF OPERATOR

Yates Petroleum Corporation

3. ADDRESS OF OPERATOR

207 South 4th Street - Artesia, NM 88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

660' FNL & 1980' FEL of Sec. 23-21S-21E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4592' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☐
☐

PULL OR ALTER CASING

☐
☐
☐
☐

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☒
☐
☐

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

Spud

REPAIRING WELL

☐
☐
☒

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Spudded a 17½" hole at 9:00 AM 12-23-77.

TD 359' - Ran 8 joints of 13-3/8" 48# K-55 (364') of casing set at 359'.
1-centralizer at 320'. Cemented w/200 sacks of Class C cement 4% CaCl.
Slurry wt. 14.8, 1.32 cu ft/sx. Compressive Strength at 70 deg 1023 psi
in 12 hours. Cement did not circulate. PD 9:30 PM 12-26-77. Filled
hole w/5 yards of Ready-mix. WOC 12 hours, cut off casing, reduced hole
to 12¼", drilled plug and tested to 600#. OK. Resumed drilling.

18. I hereby certify that the foregoing is true and correct

SIGNED

Christine J. J. J.

TITLE Geol. Secty

DATE 1-4-78

(This space for Federal or State office use)

APPROVED BY

La S. L.

TITLE ACTING DISTRICT ENGINEER

DATE JAN 6 - 1978

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

RECEIVED
JAN 4 1978
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO