

NEW MEXICO OIL CONSERVATION COMMISSION
DRAWER DD
ARTESA, NEW MEXICO

FIELD REPORT FOR CEMENTING OF WELLS

Operator <u>Berry R. Bass</u>		Lease <u>Big Eddy Unit</u>		Well # <u>60</u>	
Location of Well	Unit <u>1980 S.E.</u>	Section <u>20</u>	Township <u>21</u>	Range <u>28</u>	County <u>Eddy</u>
Drilling Contractor	<u>McVay Drilling Co.</u>		Type of Equipment <u>Rotary & start approx. 1-21-78</u>		

* Witness

APPROVED CASING PROGRAM

Size of Hole	Size of Casing	Weight Per Foot	New or Used	Depth	Sacks Cement
<u>15"</u>	<u>11 3/4"</u>	<u>42</u>		<u>500</u>	<u>300 Cms.</u>
<u>11"</u>	<u>8 5/8"</u>	<u>24+32</u>		<u>3200</u>	<u>1350 "</u>
<u>7 1/2"</u>	<u>5 1/2"</u>	<u>15.5+17+20</u>		<u>12300</u>	<u>500</u>

Casing Data:

Int
~~Surface~~ 81 joints of 8 5/8 inch 24+32 # Grade J-SS

(Approved) (Rejected)

Inspected by _____ date _____

Cementing Program

Size of hole 11" Size of Casing 8 5/8 Sacks cement required 925

Type of Shoe used Float Float collar used Reg. Btm 3 jts welded Yes

TD of hole 3200 Set 3217 Feet of 8 5/8 Inch 24+32 # Grade J-SS

New-used csg. @ 3200 with see Below sacks neat cement around shoe

+ _____ sacks _____ additives

Plug down @ 6:15 (AM) (PM) Date 2/5/78

Cement circulated Yes No. of Sacks _____

Cemented by _____ Witnessed by _____

Temp. Survey ran @ _____ (AM) (PM) Date _____ top cement @ _____

Casing test @ _____ (AM) (PM) Date _____

Method Used _____ Witnessed by _____

Checked for shut off @ _____ (AM) (PM) Date _____

Method used _____ Witnessed by _____

Remarks: DV Tool @ 800'

1st Stage - Pumped 475 SX Hall Lite w/ 1/4" Flocele + 276CC + 200 SX (less 4/276CC)
Circ 40 SX - Plug down @ 1:45 PM

2nd Stage - Pumped 150 SX Hall Lite w/ 1/4" Flocele + 276CC + 100 SX (less 4/276CC)
Circ 50 SX - Plug down @ 6:15 PM

5 Centralizers ran + 2 baskets - 1 basket above DV tool + 1 below tool