

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

OIL CONS COMMISSION
Drawer DD
Artesia, NM 88210

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

DEC 17 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Texaco Exploration and Production Inc.

3. Address and Telephone No.

P.O. Box 730, Hobbs, NM 88240

505-393-71917

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

UNIT LETTER G, 2110' FNL & 1980' FEL
SEC. 34, T-22-S, R-26-E

5. Lease Designation and Serial No.

NM-31202

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

FEDERAL 34 #1

9. API Well No.

30-015-22437

10. Field and Pool, or Exploratory Area

WILDCAT BRUSHY CANYON

11. County or Parish, State

EDDY COUNTY, NEW MEXICO

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☒ Other EXTENSION OF TA STATUS

- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recommendation Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Texaco Exploration and Production Inc. requests an extension of one year of the Temporarily Abandonment Status of the above well. T.A. status was approved on 12-30-92 based upon the results of a casing integrity test conducted on 12-1-92 and witnessed by BLM representative Don Early. TEPI requests TA status on this well through 12-1-94. (Copy of 12-1-92 test chart on back)

This well was originally TA'D on 8-14-88 with a 7 5/8" CIBP set @ 4915' and capped with 35' cement. (PBSD 4880')

TH APPROVED FOR 12 MONTH PERIOD
ENDING 12/1/94

12/97

RECEIVED

DEC 6 11 01 AM '93

RECEIVED

14. I hereby certify that the foregoing is true and correct

Signed *Joe G. Lara*

Title ENGINEER'S ASSISTANT

Date 12-2-93

(This space for Federal or State office use)

Approved by (ORIG. SGD.) JOE G. LARA

Conditions of approval, if any:

Title Petroleum Engineer

Date 12/14/93

