

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

RECEIVED
AUG 15 1991

O. C. D.

WELL API NO. 30-015-22449
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. L-4995
7. Lease Name or Unit Agreement Name Cities JH State
8. Well No. 1
9. Pool name or Wildcat Undesignated
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4612' GR

SUNDRY NOTICES AND REPORTS ON WELLS ARTESIA, OFFICE
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE 'APPLICATION FOR PERMIT'
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator YATES PETROLEUM CORPORATION
3. Address of Operator 105 South 4th St., Artesia, NM 88210	4. Well Location Unit Letter E : 2205 Feet From The North Line and 660 Feet From The West Line Section 36 Township 21S Range 21E NMPM Eddy County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Plugback, swab test <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-21-91. POOH w/RBP and pkr. Checked annulus between 8-5/8" and 5-1/2" casing. No flow of gas, water or oil. Welded lift nipple on 5-1/2" casing. RU wireline. Cut 5-1/2" casing 3900' from surface. Pulled and laid down. Notified NMOCD of plugback. RIH w/2-3/8" tubing open ended to 5260'. Spotted 25 sx Class "C" cement plug from 5260-5013'. Pulled up to 4800'. Reversed tubing clean. Tagged plug at 5000'. Pulled up to 4625'. Spotted 30 sx plug from 4625-4329'. Pulled up to 4100'. Reversed tubing. Tagged top of plug at 4340'. Pulled up to 3950'. Spotted 30 sx plug from 3950-3850'. (50' in and 50' out of casing stub at 3900'). Pulled up to 3700'. Circ clean. Tagged top of plug at 3860'. Pulled up to 3100'. WOC. Swabbed from seating nipple.

5-29-91. Recovered 22 bbls of black water. Released rental equipment.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Juanita Goodlett TITLE Production Supervisor DATE 8-14-91

TYPE OR PRINT NAME Juanita Goodlett TELEPHONE NO. 505/748-1471

(This space for State Use)

ORIGINAL SIGNED BY
MIKE WILLIAMS
SUPERVISOR, DISTRICT II

APPROVED BY

TITLE

DATE

AUG 22 1991

CONDITIONS OF APPROVAL, IF ANY: