Form 9-331	Form Approved. Budget Bureau No. 42-R1424
UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR	NM-17200
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do not use this form for proposals to drill or to deepen or plug back to a differen reservoir, Use Form 9-331-C for such proposals.)	8. FARM OR LEASE NAME
	Southeast Indian Basin
well X well X other	9. WELL NO.
2. NAME OF OPERATOR	10. Field OR WILDCAT NAME Undesignated
Chama Petroleum Company 3. ADDRESS OF OPERATOR	Indian Basin Upper Penn
P.O. Box 31405, Dallas, Texas 75231	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4 LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 1.	7 AREA Sec. 23, 1-22-5, R-23-E
below.) 660' FNL & 660' FEL	12. COUNTY OR PARISH: 13. STATE
AT SURFACE: Same AT TOP PROD. INTERVAL: Same	Eddy New Mexico
AT TOTAL DEPTH:	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE	
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 4141.5' GL
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	
FRACTURE TREAT	
REPAIR WELL	(NOTE: Report results of multiple completion or zone - change on Form 9-330.)
PULL OR ALTER CASING	
ABANDON*	
<ol> <li>DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly s including estimated date of starting any proposed work. If well i measured and true vertical depths for all markers and zones perti</li> </ol>	
1-17-83: 150# tubing pressure, 350# casing pre fluid came up to 500 to 800' from sur 55 bbls. load water with fluid level build up to 450#, blew down casing, c closed in well	essure, fluid level 3000' from surface, face after 4 runs, swabbed estimated at seating nipple, casing pressure only had 50 to 60 fluid coming in hole,
down casing, pulled out of hole, remo perforating nipple with bull plug on Guiberson tension packer, perforating set packer as low as possible in bot entry in 1 hr., closed in well	oved well head & BOP, trip in hole with bottom, repture disk on bottom of g nipple and seating nipple on top, tom of 8 5/8" casing at 2261', no fluid
Subsurface Safety Valve: Manu. and Type	Set @ Ft.
18. I hereby certify that the foregoing is true and correct	
SIGNED ACCEPTED FOR RECORD	
Lis nace the rederat of Sta	te office doey
APPROVED BY CONDITIONS OF APPROVIAN & 8 1983	DATE
MINERALS MANAGEMENT SERVICE ROSWELL, NEW MEXICO	