

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TR "CATE"  
(Other instruct on re-  
verse side)Form approved.  
Budget Bureau No. 42-R1424.5. LEASE DESIGNATION AND SERIAL NO.  
NM 13405

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Roaring Springs ~~Re~~ Fed

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Wildcat

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREASec. 14-20S-26E  
Unit J NMPM

12. COUNTY OR PARISH 13. STATE

Eddy

NM

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a permit reserved.  
Use "APPLICATION FOR PERMIT" for such proposals.)

RECEIVED

1. OIL ☐ GAS ☐ OTHER ☒ Dry JUL 9 19792. NAME OF OPERATOR  
Yates Petroleum Corporation ✓3. ADDRESS OF OPERATOR  
207 South 4th Street - Artesia, NM 88210  
O.C.C. ARTESIA, OFFICE4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface  
1980' FSL & 1980' FEL of Section 14-20S-26E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3313' KB

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON\* ☒CHANGE PLANS ☐

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT\* ☐(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any  
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-  
nent to this work.)\*

TD 10425'; PBTD 2533'. Verbal approval was given by USGS, Artesia, New Mexico to plug well as follows: Ran 74 joints of 2-3/8" tubing to 2320'. Circulated hole and mixed mud, spotted 65 sacks of cement plug. PD 10:15 AM 6-5-79. Top of cement at 2124'. Laid down tubing, removed casing head and BOP, set 10' sack of cement plug to surface and installed a dry hole marker.

RECEIVED

JUN 12 1979

U.S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

*Christina J. ...*

TITLE

Geol. Secty.

DATE

6-12-79

(This space for Federal or State office use)

APPROVED BY

*Joe M. Lara*

TITLE

ACTING DISTRICT ENGINEER

DATE

JUL 6 - 1979

CONDITIONS OF APPROVAL, IF ANY: