

Copy to 27

N. M. O. C. G. COPY

Form 9-331  
Dec. 1973

Form Approved.  
Budget Bureau No. 42-R1424

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☒ other ☐  
2. NAME OF OPERATOR  
Continental Oil Company ✓  
3. ADDRESS OF OPERATOR  
P.O. Box 460 Stanton, N.M. 88220  
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: 960' 354' 1980' 7WU  
AT TOP PROD. INTERVAL:  
AT TOTAL DEPTH: -

5. LEASE  
N.M. 038750-34458  
6. IF INDIAN, ALLOTTEE OR TRIBE NAME  
7. UNIT AGREEMENT NAME  
8. FARM OR LEASE NAME  
Federal 34  
9. WELL NO.  
1  
10. FIELD OR WILDCAT NAME  
Cat Claw - Marrow  
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
Sec 34 T-20S. R-26E  
12. COUNTY OR PARISH  
Eddy  
13. STATE  
N.M.  
14. API NO.  
15. ELEVATIONS (SHOW DF, KDB, AND WD)  
3257.8' 62

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:	SUBSEQUENT REPORT OF:
TEST WATER SHUT-OFF <input type="checkbox"/>	<input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	<input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	<input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	<input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	<input type="checkbox"/>
MULTIPLE COMPLETE <input type="checkbox"/>	<input type="checkbox"/>
CHANGE ZONES <input type="checkbox"/>	<input type="checkbox"/>
ABANDON* <input type="checkbox"/>	<input type="checkbox"/>
(other) <u>set 16" surf. cas.</u>	

RECEIVED

DEC - 8 1978

O. C. G.  
ARTESIA, OFFICE

RECEIVED  
DEC 6 1978

U.S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

(NOTE: Report results of multiple completion zone change on Form 9-331-C)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

11-23. MIRU - spud well @ 1:00pm  
11-24 could not drill 20" hole deeper than 275' set surf. csg bs follows:  
Ran GS, 47' shoe jt., F.C., 3jts 16", 65#, H-40, STfc landed @ 275'  
cmt. w/ 450 sx class "C" cmt. circ 100sx to surf.  
11-26 test csg to 600+ held ok. began drly ahead

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Wm. A. Butterfield TITLE Administrative Supervisor DATE 12-5-78

APPROVED BY Joe J. Lara (This space for Federal or State office use)  
CONDITIONS OF APPROVAL, IF ANY: \_\_\_\_\_ TITLE ACTING DISTRICT ENGINEER DATE DEC - 6 1978

4563 artesial (5)  
FILE (1)