

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

MAR 29 1991

O. C. D.

WELL API NO.
30-015-22938

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
V-1798

7. Lease Name or Unit Agreement Name

South Soapberry AIH State

8. Well No.
1

9. Pool name or Wildcat
Undes. Carlsbad Delaware

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER RE-ENTRY

2. Name of Operator
YATES PETROLEUM CORPORATION (505) 748-1471

3. Address of Operator
105 South 4th St., Artesia, New Mexico 88210

4. Well Location
Unit Letter M : 660 Feet From The South Line and 660 Feet From The West Line
Section 18 Township 21S Range 26E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3311' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: RE-ENTRY ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-19-91. Clean location. Dug out cellar. RUPU. Drilled cement 15' to 45'. Fell out of surface plug. Tagged 2nd cement plug @ 492'. Drilled cement to 604'. Fell out of cement. Tagged 3rd cement plug 2616', drilled cement to 2680'. Circulated hole clean. Drilled out cement plug @ 2612'. TIH to 4253' and tag cement plug. Circulate hole clean. TOH w/tubing, bit and collars.

3-22-91. TIH w/bit, collars and tubing to 4150'. Reverse circulate bottom up. TOH. Lay down drill collar. RU and ran 97 joints (4154') of 5 1/2" 15.5# J-55 casing. Float shoe @ 4148'. Float collar @ 4128'. RU and cement w/700 sx Class "H" + 5#/sx CSE + .5% CF-14. PD 3:20 AM

3-22-91. Plug did not bump. WOC 3 days.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Juanita Goodlett TITLE Production Supervisor DATE 3-26-91

TYPE OR PRINT NAME Juanita Goodlett TELEPHONE NO. 505/748-1471

(This space for State Use)

ORIGINAL SIGNED BY
MIKE WILLIAMS

APR 29 1991

APPROVED BY SUPERVISOR, DISTRICT II TITLE DATE

CONDITIONS OF APPROVAL, IF ANY