STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT DISTRIBUTION HANTAGE CONSERVATION DIVISION P. O. BOX 2088MAY U2 1984	Form C-103 Revised 10-1-70
TILE SANTAFE, NEW MEXICO, C.D.	ta. Indicate Type of Lesse
LAND OFFICE .	State X Fre
	L-4678
SUNDRY NOTICES AND REPORTS ON WELLS 100 NOT USE THIS FORM FOR PROFONALS TO DATE ON TO STEPTIN OF PLUG BACK TO A DIFFERENT ACSERVOIR. USE "APPLICATION FOR PERMIT -" IFORM C-1013 FER SUCH PROFONALS.]	
1. OIL GAB X WELL WELL X OTHER-	7, Unit Agreement Nanie
2. Name of Operator	8. Farm of Lease Name
Amoco Production Company V 3. Address of Operator	State IE 9. Well No.
P. O. Box 68, Hobbs, NM 88240	1
4. Location of Well L 2170 South 990	10. Field and Pool, or Wildcat
UNIT LETTER 2170 FEET FROM THE South Line and 990 FEET FROM	Happy Valley Morrow
THE West LINE, SECTION 16 TOWNSHIP 22-S RANGE 26-E HMPM.	
15. Elevation (Show whether DF, RT, GR, etc.) 3567' RDB	12. County Eddy
^{16.} Check Appropriate Box To Indicate Nature of Notice, Report or Oth	<u> </u>
NOTICE OF INTENTION TO: SUBSEQUENT	
PERFOAM REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	PLUG AND ABANDONMENT
PULL OR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JOB CONTRACT AND CEMENT JOB CONTRACT.	stablish production 🛛 🕅
from temporarily abando	oned intervals.
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1103.	estimated date of starting any proposed
Moved in service unit 8-30-83. Installed blowout preventer, released tubing and packer. Fished 1" diameter shear disc bar. Ran 4-3/8" sho (jt. wash pipe, four 3-1/2" drill collars, and tubing. Drilleout cas set at apx. 11360'. Fished bar and drilled out cast iron bridge plug Ran 3 jts. 2-3/8" tubing, 1.81 F nipple 1 joint off bottom, packer, on Tubing tagged at 11660'. Raised tubing to 11081 and packer set at 109 sure tested packer to 500 psi, tested OK. Removed blowout preventer a Moved in swab unit 9-9-83. Swabbed well 16 days, last 24 hrs. initial and final fluid level 10,100'. Connected well to pipeline 9-29-83 and Flow tested 2 days, last day flowed 2 bbl water in 2 hrs. and died. O line 10-6-83, no flow for 72 hrs. Moved in swab unit 10-8-83. Swab t last day initial fluid level 6000' from surface and final fluid level Moved off swab unit 10-11-83. Moved in service unit 12-29-83. Releas tubing, and ran 4.343 gauge ring to 11660'. Ran cast iron bridge plug Ran 1 jt 2-3/8" N-80 tubing, F nipple, 2 jts. 2-3/8" N-80 tubing. Tai and packer set at 10971'. Moved off service unit 1-2-84 and began swa 15 swab runs in 10 hrs. and recovered 23 bbl load water. Moved out sw in service unit 1-16-84 and acidized with 3600 gal 7-1/2% HCL and 900 0+5-NMOCD,A 1-JR. Barnett, HOU Rm. 21.156 1-F. J. Nash, HOU Rm. 4.200	e, 1/4" cut right, t iron bridge plug set at apx. 11535'. -off tool, and tubing. 80'. Loaded and pres- nd installed tree. fluid level was 6500' began flow testing. pened well to sales ested for 3 days, 10200', from surface. ed packer, pulled and set at 11615'. 1pipe landed at 11069' b testing. Made ab unit 1-5-84. Moved gal methanol. Flushed
NICHTO Jan C. Clark Assist. Admin. Analyst	DATE 4-26-84
Original Signed By	f II
Loslie A. Elements	MAY 0 3 1984
CONDITIONS OF APPROVAL, IF ANY:	

with 56 bbl 10# brine containing 2% KCL. Swab tested 4 days, last 10 hrs. recovered 20 bbl water. Flow tested 11 days shut well in for 96 hrs, shut in tubing pressure 1700 psi. Openedwell up and flow decreased to 35 MCFD from 350 MCF in 24 hrs. Well is currently shut-in.