

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☒ other2. NAME OF OPERATOR
Tenneco Oil Company

3. ADDRESS OF OPERATOR

6800 Park Ten Blvd., Suite 100, NEW MEXICO

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 1980' FSL & 660 FWL

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐CHANGE ZONES ☐ABANDON* ☐

(other) Spudded Well on 6-27-80

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

6-27-80 Spudded @ 9:30 p.m. 6-27-80 7-01-80 Ran 10jts. of 13 3/8" 54.5 #K-55 ST&C 8rd casing set @ 410'. Cemented w/300 sxs Thix. set + 1/2 #/sx F.S. + 2% CaCl₂ + 350 sxs class "C" 2% CaCl₂ No returns 14.6#/gal. 1.32 yield. R/U 1" Line to cmt. to surface Cmt. w/100 sxs class "C" 4% CaCl₂. Tag cmt @ 218' w/1" pipe cmt. basket @ 258'. Recement w/1" Laid 200 sxs plug 200' to surface of ground. Cmt standing 1' below cellar floor. WOC. 33. Tested csg. w/600 psi OK.

Subsurface Safety Valve: Manu. and Type

Set @ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

DATE

(This space for Federal or State office use)

APPROVED BY: OFF. BARRY W. CHESTER TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: