

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLI .TE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-11946

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

RECEIVED

1. OIL WELL ☐ GAS WELL ☐ OTHER Dry Hole

2. NAME OF OPERATOR

Yates Petroleum Corporation ✓

AUG 28 1980

3. ADDRESS OF OPERATOR

207 S. 4th St., Artesia, NM 88210

O. C. D.

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

1980 FSL & 2030 FWL, Sec. 11, T21S, R22E, NMPM

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Searle ML Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Und. Morrow

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Unit K

Sec. 11-T21S-R22E

12. COUNTY OR PARISH 13. STATE

Eddy

N. Mex.

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4164

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other)

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other)

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☒

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Verbal approval was given by Mr. Jim Gillham, U.S.G.S., Roswell, NM, 8/4/80 to plug well - the well was plugged as follows:

Plug #1: 9085-8935' w/35 sacks Class H cement.
Plug #2: 8425-8275' w/35 sacks Class H cement.
Plug #3: 7200-7050' w/35 sacks Class H cement.
Plug #4: 5240-5140' w/35 sacks Class H cement.
Plug #5: 4070-3970' w/35 sacks Class H cement.
Plug #6: 1290-1190' w/35 sacks Class H cement.
Plug #7: 169-0 (Surface) w/25 sacks Class H cement

RECEIVED
AUG 12 1980
U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

Installed regulation abandonment marker. Location will be restored according to U. S. G. S. requirements when received.

18. I hereby certify that the foregoing is true and correct

SIGNED

Albert R. Stall

TITLE

Engineer

DATE

8/11/80

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: