STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

U CJAMBYNNY UPA TOM.	LFAI	11141C
we er conice neceives	3	
DISTRIBUTION	Ĭ	
BANTA PE	1	
FILE		V
U.S.G.S.		
LAND OFFICE		<u> </u>
OPERATOR	77	

CONDITIONS OF APPROVAL, IF ANYE

OIL CONSERVATION DIVISION P.O. BOX 2088

Form	C-	103		
Pavis	اء م	10-	1 - 75	1

BISTATION		CANTA EE NEW	MEXICO 97501		Kevised	10-1-78
SANTA PE	SANTA FE, NEW MEXICO 87501		[3a Ind	icate Type of Lease		
U.S.O.S.	7	HIGH AND IO	o o	l l	F5F□	•••
LAND OFFICE	_	يوهو يون		Į.		
OPERATOR			1	e Oil & Gas Lease No.	•	
		artema, Offi	CE		L-4861	
CIALIZ	DV NOTICES	AND REPORTS ON	WELLS			//////
ONNO PER THE SEN TON OOL	ADPOSALS TO DRILL	OR TO DEEPEN OR PLUG B	ACK TO A DIFFERENT RESERVOIR			/////
USE TAPPLICA	ATTON TON PERMIT			7. Uni	L Agreement Name	****
OIL 図 GAS □						
weit X weit	OTHER-			8. Fax	m or Leuse Name	
, Name of Operator						
MWJ Producing Company				9. Wel	State GWA	
3. Address of Operator				9. 001	_	
1804 First National B	ank Buildin	ig, Midland, Tex	as 79701		1	
4. Location of Well					eld and Pool, or Wilde	at
т	2180	South	660	Aval	on Delaware	
UNIT LETTER	·	PROM TAL				
Fact	36	20.5	27E			//////
THE East LINE, SEC	TION	TOWNSHIP	RANGE	NMPM.		//////
mmmmm	THINK	Elevation (Show whether	DF RT GR etc.)	12. Cc	ownly XHHH	4444
	//////////////////////////////////////		171 , 161 , ON , CICI,	†	ldy	//////
	7/////	3293.7 Gr.			177777	77777
16. Check	Appropriate	Box To Indicate N	lature of Notice, Repo	ort or Other Da	ta	
	INTENTION T		subs	EQUENT REP	ORT OF:	
1101102						
		PLUG AND ABANDON	REMEDIAL WORK		ALTERING CASING	П
PERFORM REMEDIAL WORK			COMMENCE DRILLING OPHS.	ī	PLUG AND ABANDON	MENT
TEMPORARILY ABANDON			CASING TEST AND CEMENT JQ	. H		
PULL OR ALTER CASING		CHANGE PLANS	OTHER Perf'd.		ing on nump.	
		Г—	OTHER TELL U.	ACTO & CCSC.	tilg off pump.	— Ш
OTHER		L				
17. Describe Freposed or Completed		111	ails and sive pertinent dates	including estimat	ed date of starting any	proposed
17. Describe Proposed or Completed work) SEE RULE 1103.	Operations (Crear	ry state all pertinent det	aits, and give periment abres	,	, ,	• •
·		- •		FO! 1 474		
MI RU PU. Ran Collar	locater log	g; Perf'd. at 4	724-4731'; 4/40-4/	58' and 4/64	1-4/66. W/Z SP	F.
Ran tubing and set pa	icker at 46:	54'. Acidized w	ith 500 gal. 15% H	CL Acid at :	2 BPM at 900	
psi. Swabbed for 2 hr	:s. RU Dowe!	ll and Acidized	with 3,000 gal. 1	5% HCL. and	72 ball seale	rs.
Ran pump and rods, fl	anged up.	Installed pumpin	ng unit. Now testi	ng well on p	pump.	
		-				
		•				
		•				
		•				
						
16. I hereby certify that the informat	ion above is true	and complete to the best	of my knowledge and belief.		•	
A = A = A = A)					
V 73. 10 l	llk -	T.T. T A	gent		TE 10/28/80	
SICHED						
	Л	•			007 001	1009
1.500	40000		_		OCT 301	UOCI
APPROVED BY _ (U, U,)	- weren	TITLE	WPERVISOR, DISTRICT	-11		