

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)

Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM - 13232

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

GOVERNMENT "AN" Com.

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Sec. 3-T20S-R28E

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 3-T20S-R28E

12. COUNTY OR PARISH

13. STATE

Eddy

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED

1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

CITIES SERVICE COMPANY

3. ADDRESS OF OPERATOR

P. O. Box 1919 Midland, Texas 79702

ARTESIA, OFFICE

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface

660' FNL & 1980'FWL of Sec. 3-T20S-R28E, Eddy County, New Mex.

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3284' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON\*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any  
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-  
nent to this work.) \*

T.D. 3000' lime. Prep to drill ahead. Drilled 12 1/4" hole from 425' to a T.D. of 3000'  
Lime. Ran & set 26 jts. (1095.86') 8-5/8" OD 32# K55 & 46 jts. (1881.34) 8-5/8" OD 24#  
K55 csg @ 2995' & cemented w/1140 sacks of Halliburton lite + 1/4# Flocele & 8# salt/sk  
+ 300 sacks of CL C + 2% CaCl<sub>2</sub>. Plug down at 1130 MDT on 7-20-81. Had good circ. but  
cement did not circulate to surface. WOC 8 hours. Ran temp. survey. Top of cement  
at 420'. Ran 1" pipe in 8-5/8" annulus and cemented w/170 sx of Cl C cement. Circulated  
5 sacks of cement to pit. WOC 18 hours. Tested 8-5/8" casing to 1500# - OK.

RECEIVED  
JUL 28 1981

OIL & GAS  
U.S. GEOLOGICAL SURVEY  
ROSWELL, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Reg. Oper. Mgr.-Drilling

DATE 7-23-81

(This space for Federal or State office use)

ACCEPTED FOR RECORD  
ROGER A. CHAPMAN

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY

U.S. GEOLOGICAL SURVEY  
ROSWELL, NEW MEXICO

See Instructions on Reverse Side