

NM OIL CONS. COMMISSION
Denver DD
Artesia, NM 88210

Form 9-331
Dec. 1973

Form Approved.
Budget Bureau No. 42-R1424

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

C/SF
SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☒ other ☐
2. NAME OF OPERATOR
Getty Oil Company
3. ADDRESS OF OPERATOR
P.O. Box 730 Hobbs, NM 88240
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: Unit Ltr. H, 1980' FNL & 660' FEL
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:
TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) Spud

SUBSEQUENT REPORT OF:

RECEIVED
APR 13 1982
OIL & GAS
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO
X

5. LEASE
15881
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME
Burton Flat "11" Federal
9. WELL NO.
1
10. FIELD OR WILDCAT NAME
Undesignated
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 11, T20S, R29E
12. COUNTY OR PARISH
Eddy
13. STATE
NM
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)
3315' GL

RECEIVED

MAY - 3-1982

O.C.D.
ARTESIA, OFFICE

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

4/2/82 Sharp Rig No. 62 moved in and rigged up; spudded 17 1/2" hole @ 1:00 p.m.
4/3/82 Drilled 17 1/2" hole to 662'. Ran 6 jts. 13 3/8" K-55 54.50# and 10 jts. 13 3/8" H-40 48# casing and set at 659'. Howco cemented w/400 sxs. class "C" cement, .4% gel & 2% CaCl. Tailed in w/200 sxs. class "C" cement and 2% CaCl. Total cement - 600 sxs. Circulated 75 sxs. WOC.
4/4/82 WOC 18 hours, pressured up on casing to 1200# for 30 minutes. OK.

Subsurface Safety Valve: Manu. and Type _____

18. I hereby certify that the foregoing is true and correct

SIGNED Dale R. Crockett TITLE Area Superintendent

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE _____

ACCEPTED FOR RECORD
APR 29 1982
U.S. GEOLOGICAL SURVEY
ROSWELL, NM