Form 9-331

P" OTT COMS. COMMISSION

Form Approved.

Budget Bureau No. 42-R1424

Dec. 1973		
UNITED STATES Artesia, NM 882		
DEPARTMENT OF THE INTERIOR	NM -082775 5 3 2 2 2	
GEOLOGICAL SURVEY	6. IF INDIAN, ALLO TEE OR TRIBE NAME	7
GEOLOGICAL SURVET	Santa Single	1
	7. UNIT AGREEMENT NAME NAME	
SUNDRY NOTICES AND REPORTS ON WELLS		
(Do not use this form for proposals to drill or to deepen or plus back to a different reservoir. Use Form 9–331–C for such proposals.)	Saladar Unit	
reservoir, Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME	
1. oil gas		
	9. WELL NO. 🥞 👙 🛴 🛴 🗒 🐰	
2. NAME OF OPERATOR OCT 1 5 1982	13 ទី១៩៩ និ ១៩៩	<u>.</u>
Rarbor Oil Inc	10. FIELD OR WILDCAT NAME	
3. ADDRESS OF OPERATOR	Salada r- Yates	
D. O. D. 1650 Coulobed ARTESIA/OFFICE	11. SEC., T., R., M., OR BLK. AND SURVEY	r OR
P. O. Box 1658 Carlsbad, MRTES 29 FICE	AREA	
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	Sec. 33, T20S, R28E 1	
below.) AT SURFACE:1315' FSL and 1980' FWL	12. COUNTY OR PARISH 13. STATE	
		1
AT TOP PROD. INTERVAL:	Eddy By MM No.	
AT TOTAL DEPTH:	14. API NO. 역유적인 및 유행으로	
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	<u> </u>	
REFORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND	WD)
	GR 31964 9 7 8 200 8	
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	20 g 4 g 5 g 7 g	,
TEST WATER SHUT-OFF	그 그 그 그 그 그 그 그 뭐 그 그 그 그 그 그 그 그 그 그 그	
FRACTURE TREAT		
SHOOT OR ACIDIZE		
REPAIR WELL	(NOTE: Report results of multiple completion or change on Form 9-330.) 基 音楽景	·zone
PULL OR ALTER CASING U		
MULTIPLE COMPLETE		
CHANGE ZONES	Secretary of the property of t	} 6
(other) complete drilling & cement casing	स क्षेत्रहें या दूर्वाहर	
(Other) Compage Transfer	3 88 4 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6	<u> </u>
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly stat	e all pertinent details, and give pertinent d	ates,
including actimated date of starting any proposed work. If well is d	irectionally drilled, give subsurface locations	ξand
measured and true vertical depths for all markers and zones pertiner	ir to this work.). 표정 # 그 그 # 그 # 그 # 그 # 그 # 그 # 그 # 그 # 그	
1 :11: - 7 20 02 Ded11 od to	a donth of 682 trace at 80 5	:
Began drilling 7-28-82. Drilled to	a depth of dozal-dec do a sal	:
of 7-5/8", 26.40# casing to shut of	rr surrace water and cemented	
with 15 sax. Ran $682'3''$ of $4\frac{1}{2}''$, 1	1.60# casing and cemented 3	-
with 230 sax. Cement circulated to	o surface. Will install	_
pumping equipment as soon as possi	ble. Completed drilling on 5.5	
8-3-82.	<u>ी जे जे लिए</u> के किस के किस सिक्त के किस	-
		3
	·	7
		:
	그림을 다음 모양 시작한다.	
	그 그 그 그 그 그 원일속속하는 사회 나는 그	
	그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그	
Subsurface Safety Valve: Manu. and Type	Set @ 3	Ft.
	# # # # # # # # # # # # # # # # # # #	
18. I hereby certify that the foregoing is true and correct		Y
TITLE President	DATE 8-5-825	킬
SIGNED TITLE President	# # # # # # # # # # # # # # # # # # #	
ACCEPTED FOR RECORD (This space for Federal or State of	fice use)	
(ORIG. SGD.) DAVID R. GLASS		£.
APPROVED BY	DATE	<u> </u>
CONDITIONS OF APPROVAL, IF ANY:		74
0CT 1 4 1982	加到時間對心學的	U
	NCASSON 100	
U.S. GEOLOGICAL SURVEY	THE STATE OF THE S	
ROSWELL, NEW MEXICO Instructions on Reverse	Side JUS AUG 9 1982 111	
KOSVVELL, MENT MENTOS		