

RECEIVED

NM OIL CONS. COMMISSION
DRAWER DD
Artesia, NM 88210

Form Approved.
Budget Bureau No. 42-R1424

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
MINERALS MGMT. SERVICE
ROSWELL, NEW MEXICO

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☒ gas well ☐ other ☐
2. NAME OF OPERATOR Exxon Corporation
3. ADDRESS OF OPERATOR P. O. Box 1600, Midland, Texas 79702
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 660' FNL & 1980' FEL of Sec.
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:	SUBSEQUENT REPORT OF:
TEST WATER SHUT-OFF	<input checked="" type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>
CHANGE ZONES	<input type="checkbox"/>
ABANDON*	<input type="checkbox"/>
(other)	

5. LEASE NM-01119
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME Yates Federal C
9. WELL NO. 3
10. FIELD OR WILDCAT NAME Undesignated Burton Flat Delaware
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 31, T20S, R28E
12. COUNTY OR PARISH Eddy 13. STATE New Mexico
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD) Later

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Spudded 12 1/4" hole at 6:00 a.m. 9-21-82
Drilled 12 1/4" hole to 608'.
Ran 14 jts 8 5/8" 24# K-55 csg set at 605'. Cmt w/400 sx Class "C" and tailed w/25 sx C1 "C". Plug down at 7:00 a.m. 9-22-82.
Cmt did not circ. WOC. Top of cmt 386' - Temp survey.
Ran 1" Pipe to 384'. Cmt w/165 sx TOC - 377', Cmt w/50 sx TOC 217', cmt w/185 sx, cmt to surface, Job comp 6:00 a.m. 9-23-82
Tested 8 5/8" csg at 10:30 p.m. 9-23-82 w/1500 # - Held OK
Drilled Plug at 1:45 a.m. 9-24-82. Drilling.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED D. F. Lowe TITLE Sr. Administrator DATE October 18, 1982

APPROVED BY _____ (This space for Federal or State office use)
CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD
(ORIG. SGD.) DAVID R. GLASS
OCT 25 1982
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

*See Instructions on Reverse Side