

## CHRONOLOGICAL DAILY REPORT

### NEW MEXICO - MAINTENANCE

Avalon Bone Spring

BURTON FLAT FED B-1      Sec 1, T21S, R27E      Eddy Co., NM

Operator: Presidio Exploration, Inc.      WI: 1.00      NRI: .8540509

Job type: Recomplete to the Brushy Draw through perms @ 4560-75' & test. If productive, stimulate & complete. If non productive, set plug & perf 4395-4430' & test. Fracture stimulate & complete.

11/17/94      Well pumping to tank; 22 BO, 320 BW.

11/18/94      Well pumping to tank; 11 BO, 310 BW. (both engines down overnight)

11/19/94      Well pumping to tank; 17 BO, 434 BW.

11/20/94      Well pumping to tank; 19 BO, 505 BW.

11/21/94      Well pumping to tank; 11 BO, 271 BW. (#1 motor down)