

## CHRONOLOGICAL DAILY REPORT

### NEW MEXICO - MAINTENANCE

Avalon Bone Spring

#### BURTON FLAT FED B-1

Sec 1, T21S, R27E Eddy Co., NM

Operator: Presidio Exploration, Inc. WI: 1.00 NRI: .8540509

Job type: Recomplete to the Brushy Draw through perfs @ 4560-75' & test. If productive, stimulate & complete. If non productive, set plug & perf 4395-4430' & test. Fracture stimulate & complete.

11/17/94 Well pumping to tank; 22 BO, 320 BW.

11/18/94 Well pumping to tank; 11 BO, 310 BW. (both engines down overnight)

11/19/94 Well pumping to tank; 17 BO, 434 BW.

11/20/94 Well pumping to tank; 19 BO, 505 BW.

11/21/94 Well pumping to tank; 11 BO, 271 BW. (#1 motor down)

11/22/94 Well pumping to tank; 34 BO, 690 BW. Changed out polish rod liner on B-2, down due to heavy rains; produced 22 BO; 520 BW.

11/23-30/94 Well stabilizing @ 8 BO, 505 BW. Combined with Burton Flat Fed. #B-2. **FINAL REPORT.**