Form 9-331 Dec. 1973

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

CONDITIONS OF APPROVAL, IF ANY:

PULL OR ALTER CASING MULTIPLE COMPLETE **CHANGE ZONES ABANDON*** (other)

Form 9–331 Eq. ()	Form Approved. Budget Bureau No. 42-R1424
UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR	NM-01119 RECEIVED BY
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON (Do not use this form for proposals to drill or to deepen or plug back reservoir. Use Form 9–331–C for such proposals.)	to a different Q C D
1. oil gas other	Yates "C" Federal 9. WELL NO.
2. NAME OF OPERATOR	35
Exxon Corporation	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Undesig. Avalon H. Carrago
P.O. Box 1600, Midland, Texas 79702 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) 563' FNL & 560' FEL of Section AT SURFACE: (Irregular Section) AT TOP PROD. INTERVAL:	tion <u>Sec. 5-21S-27E</u>
AT TOTAL DEPTH:	Eddy New Mexico
16. CHECK APPROPRIATE BOX TO INDICATE NATURE C	DF NOTICE,
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 3207 GR
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT TEST WATER SHUT-OFF	ORT OF:
FRACTURE TREAT	(NOTE: Report results of multiple completion or zone
MULTIPLE COMPLETE	change on Form 9–330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Spud 17 1/2" hole at 4:15 AM. 12-28-83

12-29-83 Set 13 3/8", 48#, H-40 csg. @ 629' w/650 sx Lite tailed w/300 sx C1C. Cmt. circulated. Test csg. to 1500#. WOC 34 hrs., 30 min.

Subsurface Safety Valve: Manu. and Type Set @ 18. I hereby certify that the foregoing is true and correct Unit Head January 4, TITLE . DATE (This space for Federal or State office use) ACCEPTED FOR RECORD APPROVED BY _ TITLE . DATE .