

IN 075
Drew
Artoria, MI 08210

Form 9-331
Dec. 1973

RECEIVED BY
JUL 09 1984
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Form Approved.
Budget Bureau No. 42-R1424

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☒ gas well ☐ other ☐
2. NAME OF OPERATOR
Exxon Corporation ✓
3. ADDRESS OF OPERATOR
P. O. Box 1600, Midland, TX 79702
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
3300' FSL and 660' FWL of Sec. 1
AT SURFACE: (SW/SW)
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	<input type="checkbox"/>		<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>		<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>		<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>		<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>		<input type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>		<input type="checkbox"/>
CHANGE ZONES	<input type="checkbox"/>		<input type="checkbox"/>
ABANDON*	<input type="checkbox"/>		<input type="checkbox"/>
(other) Set Casing	<input type="checkbox"/>		<input type="checkbox"/>

5. LEASE
NM - 46275
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
--
7. UNIT AGREEMENT NAME
--
8. FARM OR LEASE NAME
Burton Flat B Federal
9. WELL NO.
4
10. FIELD OR WILDCAT NAME
Undesig. - Bone Springs
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
1 - 21S - 27E
12. COUNTY OR PARISH
Eddy
13. STATE
New Mexico
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)
3202' GR

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

6-17-84 Spud 17-1/2" hole @ 1830 hrs.
6-18-84 Set 14 jts 13-3/8" /48#/ H-40 csg @ 621'. Cement w/ 600 sx ClC. Circ 43 sx to surface. Witnessed by BLM. WOC 41-1/2 hours before drill out. Test casing to 1000 psi for 30 min. Held OK.
6-23-84 Set 59 jts 8-5/8" / 24#/ K55 csg @ 2513 in 11" hole. Cement w/ 1400 sx Pacesetter and 100 sx ClC. Circ. to surface. WOC 21-1/2 hrs. before drill out. Test casing to 1200 psi for 30 min. Held OK.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Melba Kripling TITLE Unit Head DATE June 29, 1984

ACCEPTED FOR RECORD (This space for Federal or State office use)
APPROVED BY [Signature] TITLE _____ DATE _____
CONDITIONS OF APPROVAL IF ANY:

JUL 5 1984

[Signature]

NEW MEXICO

*See Instructions on Reverse Side